
## **ACO DRAIN**

## Sam's Club Richmond, VA














## **PROJECT PORTFOLIO**

Product: Contractor:

S100K Restoration and Recovery (R&R), Durham, NC



This trench drain, which was installed at Sam's Club in Richmond, VA, is just over 300 feet in length and surrounds the fueling area.

For this project, the old and damaged Polydrain was removed and replaced with ACO PowerDrain S100K in 2 stages in order to allow the station to remain open.

